Cannot start charging	1.The power supply does not meet requirements. 2.Unstable connection of power interface. 3.The charging distance is out of range. 4.There are other metal objects in the charging area.	Replace the adapter that match. Reinsert the power socket. Susing within the specified distance Remove metal foreign bodies	
Charging is slow	The temperature of product is too high	Keep reasonable space for heat dissipation Please wait until the temperature drops to room temperature before using the device	




120.00 mm

represents the environmental service life. In this period of time, under normal conditions of use harmful substances will not cause greater pollution to the environment or damage to human life and property.

	×					





Minimum.