



10MHz\_High\_QPSK\_1@49



ProjectNo.:2402X94972E-RF Tester:Loge Long

Date: 18.SEP.2024 16:17:44


10MHz\_High\_QPSK\_50@0



ProjectNo.:2402X94972E-RF Tester:Loge Long

Date: 18.SEP.2024 16:18:22


10MHz\_High\_16QAM\_1@49



ProjectNo.:2402X94972E-RF Tester:Loge Long

Date: 18.SEP.2024 16:19:01


10MHz\_High\_16QAM\_50@0



ProjectNo.:2402X94972E-RF Tester:Loge Long

Date: 18.SEP.2024 16:19:40


15MHz\_Low\_QPSK\_1@0



ProjectNo.:2402X94972E-RF Tester:Loge Long

Date: 18.SEP.2024 16:22:23


15MHz\_Low\_QPSK\_75@0



ProjectNo.:2402X94972E-RF Tester:Loge Long


Date: 18.SEP.2024 16:23:02

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:23:40

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:24:18

15MHz\_High\_QPSK\_1@74




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:25:24

15MHz\_High\_QPSK\_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:26:02

15MHz\_High\_16QAM\_1@74




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:26:40

15MHz\_High\_16QAM\_75@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:27:18

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:29:46

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:30:25

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:31:04

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:31:42

20MHz\_High\_QPSK\_1@99




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:33:01

20MHz\_High\_QPSK\_100@0




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:33:42

20MHz\_High\_16QAM\_1@99



ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:34:22

20MHz\_High\_16QAM\_100@0



ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 16:35:03


Spurious Emissions at Antenna Terminal

FCC Part 22H

B5 , Normal


1RB was the worst case

1.4MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:48:09

1.4MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:48:28

1.4MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:48:48

3MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:49:12

3MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:49:34

3MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:49:57

5MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:50:23

5MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:50:47

5MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:51:12

10MHz\_Low\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:51:40

10MHz\_Middle\_QPSK\_1@0(30MHz~9.49GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:52:05

10MHz\_High\_QPSK\_1@0(30MHz~9.49GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:52:31

FCC Part 27


B41 , Normal

1RB was the worst case


5MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




5MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)




5MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




10MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




10MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)



10MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




15MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 13:59:24

15MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:00:02

15MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 14:00:43

20MHz\_Low\_QPSK\_1@0(30MHz~27.9GHz)




ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:01:25

20MHz\_Middle\_QPSK\_1@0(30MHz~27.9GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 14:02:04

20MHz\_High\_QPSK\_1@0(30MHz~27.9GHz)



ProjectNo.:2402X94972E-RF Tester:Loge Long  
Date: 18.SEP.2024 11:02:45