	Report No: R3406 Issue No: 1	FCC ID: XX6STP9080 / XX6STP9280	
	Test No: T5484		
		Test Photos	Page: 1 of 6



dB Technology
|----- (Cambridge Ltd.) -----|

EMC
Testing

EMC
Consultancy

EMC
Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

REPORT ON ELECTROMAGNETIC COMPATIBILITY TESTS

Performed at:
TWENTY PENCE TEST SITE

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Sepura PLC

STP9080/STP9280

dated


4th November 2014

Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	04/11/14		Initial release		


Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*

	Report No: R3406 Issue No: 1	FCC ID: XX6STP9080 / XX6STP9280	
	Test No: T5484		Test Photos



Photograph 1 STP9080: Connected to Analyser


	Report No: R3406	FCC ID: XX6STP9080 / XX6STP9280	
	Issue No: 1		
	Test No: T5484	Test Photos	Page: 3 of 6



Photograph 2 Standalone: Radiated Emissions - Upright



Photograph 3 Standalone: Radiated Emissions - Flat


	Report No: R3406	FCC ID: XX6STP9080 / XX6STP9280	
	Issue No: 1		
	Test No: T5484	Test Photos	Page: 4 of 6



Photograph 4 With RSM: Radiated Emissions - Upright




Photograph 5 With RSM: Radiated Emissions - Flat


	Report No: R3406	FCC ID: XX6STP9080 / XX6STP9280	
	Issue No: 1		
	Test No: T5484	Test Photos	Page: 5 of 6



Photograph 6 Car Kit: Radiated Emissions - Front



Photograph 7 Car Kit: Radiated Emissions - Back

	Report No: R3406	FCC ID: XX6STP9080 / XX6STP9280	
	Issue No: 1		
	Test No: T5484	Test Photos	Page: 6 of 6



Photograph 8 STP9280: Radiated Emissions - Front



Photograph 9 STP9280: Radiated Emissions - Back