	Report No: R3538 Issue No: 1	FCC ID: XX6SC2024	
	Test No: T5950	Report Photos	Page: 1 of 4



dB Technology

|----- (Cambridge Ltd.) -----|

EMC
Testing

EMC
Consultancy

EMC
Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

REPORT PHOTOS FOR TEST

**Performed at:
TWENTY PENCE TEST SITE**

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Sepura PLC

SC2024

dated


26th January 2016

Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	11/02/16		Initial release		


Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*


	Report No: R3538	FCC ID: XX6SC2024	
	Issue No: 1		
	Test No: T5950	Report Photos	Page: 2 of 4



Photograph 1 Connected to Analyser



Photograph 2 In Environmental Chamber


	Report No: R3538	FCC ID: XX6SC2024	
	Issue No: 1		
Test No: T5950	Report Photos		Page: 3 of 4




Photograph 3 Standalone: Radiated Emissions - Upright




Photograph 4 Standalone: Radiated Emissions - Flat

	Report No: R3538	FCC ID: XX6SC2024	
	Issue No: 1		
	Test No: T5950	Report Photos	Page: 4 of 4



Photograph 5 With RSM and Charger - Radiated Emissions - Upright



Photograph 6 With RSM and Charger - Showing measuring antenna