



Tune Up Procedure

Date: December 13, 2019


Subject: Tune Up Procedure for: FCC ID: KE3-3003578

- 1. For licensed devices, Part 95J, the FCC requires a tune-up procedure and a parts list.
Rule Part 2.1033 (c):

(9) Tune-up procedure over the power range, or at specific operating power levels.

The RF Transceiver (CC1120) for the Model RIG00-16937 is fully synthesized. There is no factory tuning.

Sincerely,

By: 
(Signature/Title)

Sandi McEnergy - Agent
(Print name)