

Figure 9: RF Head Label

The following label (shown actual size) is placed on the underside (the side opposite of the view shown in figure 5) of the RF Head.




Figure 10: 47 CFR 15.19 Labelling Requirements

The label bearing the requirements of part 15.19 is located on the rear of the 9790 Programmer as shown in the figure below. This label, showing the FCC ID: LF59790, has been used since the equipment authorization granted 06/29/1995 for the 9766 RF Head. The new 9767 RF Head, which is the subject of this submittal, has additional capability to program a wider variety of implantable pacemakers. (A copy of the grant dated 06/29/1995 is enclosed for reference.)

