



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 28, 2004

RE: Behavior Tech Computer Corp.

FCC ID: E5XKB6100

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative Issues:

- 1) The block diagram should show the frequencies of all oscillators in the TX device (CFR 2.1033(a)(5)). Please provide.
- 2) Please explain why the 4 MHz oscillator is not shown in the schematic provided. Please update.
- 3) FYI....The components near the keyboard (mice, etc.), should be positioned 10 cm apart from each other. It appears these items were much farther than 10 cm apart. Please be careful of this in future applications.
- 4) Additionally, in future applications please center the keyboard on the monitor per ANSI C63.4.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.