



Antenna Compliance with FCC 15.203


There are two antennas on the Model 24965 Patient Connector.

Both antennas, the Bluetooth and the inductive telemetry, are soldered to the PCB, and as such are considered permanently attached.

Bluetooth Antenna Information

| Manufacturer | Model Number | Gain (dBi) | Description |
|--------------|--------------|------------|--------------|
| Murata | LDA212G3110K | +0.9 | Chip antenna |

Bluetooth Antenna Physical Dimensions



Inductive Telemetry Antenna Information

| Manufacturer | Model Number | Description |
|------------------------|---------------------|-------------------------|
| Precision Incorporated | 019-7353-01R 101916 | Split coil loop antenna |