



Setup Photos


Revision	Report Date	Reason for Revision
Ø	July 1, 2021	Initial Issue.



Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup



Substitution Method, Test Setup



Conducted Power Measurement Test Setup