




2422 MHz-10th Harmonics



Date: 7.MAY.2024 20:03:30




Date: 7.MAY.2024 20:03:36




Date: 7.MAY.2024 20:03:43


2427 MHz-10th Harmonics



Date: 9.MAY.2024 16:33:00




Date: 9.MAY.2024 16:33:07




Date: 9.MAY.2024 16:33:14


2437 MHz-10th Harmonics



Date: 7.MAY.2024 20:06:00




Date: 7.MAY.2024 20:06:06




Date: 7.MAY.2024 20:06:13


2442 MHz-10th Harmonics



Date: 9.MAY.2024 16:34:36




Date: 9.MAY.2024 16:34:43




Date: 9.MAY.2024 16:34:50


2447 MHz-10th Harmonics



Date: 9.MAY.2024 16:36:00




Date: 9.MAY.2024 16:36:07




Date: 9.MAY.2024 16:36:14


2452 MHz-10th Harmonics



Date: 7.MAY.2024 20:07:19



Date: 7.MAY.2024 20:07:26



Date: 7.MAY.2024 20:07:33

End of Test Report