


Label Location

Part No : Model : WU3711UBO HW ver : V, Ω, A		 	
Frequency range: MHz kHz			
FCC ID: TQ8-VT2600TAN	프린팅 영역(33X10)		
Contains FCC ID : YZP-VL3000	: 승인번호 ONLY		
This device complies with part 15 of the FCC Rules. Operation is Subject to the following two conditions : (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation			
		HYUNDAI MOBIS Co., Ltd	



Part No :
Model : WJ3731UBO

HW ver :
V, Ω, A

Frequency range:

MHz
kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :
Model : WJ3721UBO

HW ver :
V, Ω, A

Frequency range:

MHz
kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :
Model : WJ371UP BO

HW ver :
V, Ω, A

Frequency range:

MHz
kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : WU3611UBO

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : WU3631UBO

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : WU3621UBO

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : WU361UP BO

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-VT2600TAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd