


Page 1 of 59

Report No.: STS2107141W02

Conducted Spurious LTE BAND-2





LTE BAND-2



Shenzhen STS Test Services Co., Ltd.










Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.



LTE BAND-4



Shenzhen STS Test Services Co., Ltd.



LTE BAND-4



Shenzhen STS Test Services Co., Ltd.



LTE BAND-4



Shenzhen STS Test Services Co., Ltd.