



Date: June 1, 2018

Attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The Itamar Medical Ltd. WatchPat ONE, FCC ID: 2APUBWPONE, and label are so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,

Signature:

Orit Kelner
QA Manager



Itamar Medical Ltd.

9 Halamish St. P.O Box 3579, Caesarea 3088900, Israel | T: +972-4-617-7000 | F: +972-4-627-5598
US Toll Free: 1-800-206-6952 | www.itamar-medical.com