



20MHz_Low_QPSK_1@0




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 08:58:32

20MHz_Low_QPSK_100@0




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 08:59:48

20MHz_Low_16QAM_1@0




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:01:04

20MHz_Low_16QAM_100@0




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:02:19

20MHz_High_QPSK_1@99




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:03:42

20MHz_High_QPSK_100@0




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:04:58

20MHz_High_16QAM_1@99



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:06:15

20MHz_High_16QAM_100@0



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 20.DEC.2024 09:07:32


Spurious Emissions at Antenna Terminal

FCC Part 22H & IC RSS 132

B5, Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:48:12

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 19.DEC.2024 14:48:26

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:48:41

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 19.DEC.2024 14:49:10

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:49:25

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 19.DEC.2024 14:49:39

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:50:01

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:50:16

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:50:31

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:50:55

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:51:10

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 14:51:25


B2, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)









3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




3MHz_High_QPSK_1@0(30MHz~20.1GHz)






15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:28:56

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:29:15

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:29:33

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:29:55

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:30:14

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:30:33


B4, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:41:48

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:42:06

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:42:24

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:42:51

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:43:09

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:43:28

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:43:52

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:44:11

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:44:31

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:44:57

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:45:16

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:45:35

FCC Part 27 & IC RSS 130


B12, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



3MHz_High_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:00:03

5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:00:18

5MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:00:33

10MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:01:01

10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:01:16

10MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:01:32


B17, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~8.16GHz)




B66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)









3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




3MHz_High_QPSK_1@0(30MHz~18.8GHz)






15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:40:25

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:40:44

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:41:04

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:41:32

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:41:52

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 4.JAN.2025 15:42:12


B7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:48:48

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:49:10

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:49:32

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:49:57

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:50:18

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 13.JAN.2025 15:50:40


B41, Normal

1RB was the worst case


B41_5MHz_Low_QPSK_1@0(30MHz~25.375GHz)




B41_5MHz_Middle_QPSK_1@0(30MHz~25.95GHz)




B41_5MHz_High_QPSK_1@0(30MHz~26.525GHz)




B41_10MHz_Low_QPSK_1@0(30MHz~25.4GHz)




B41_10MHz_Middle_QPSK_1@0(30MHz~25.95GHz)




B41_10MHz_High_QPSK_1@0(30MHz~26.5GHz)




B41_15MHz_Low_QPSK_1@0(30MHz~25.425GHz)




B41_15MHz_Middle_QPSK_1@0(30MHz~25.95GHz)




B41_15MHz_High_QPSK_1@0(30MHz~26.475GHz)




B41_20MHz_Low_QPSK_1@0(30MHz~25.45GHz)



B41_20MHz_Middle_QPSK_1@0(30MHz~25.95GHz)




B41_20MHz_High_QPSK_1@0(30MHz~26.45GHz)




B71, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




5MHz_High_QPSK_1@0(30MHz~7.98GHz)




10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



10MHz_High_QPSK_1@0(30MHz~7.98GHz)




15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:27:44

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:27:59

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:28:14

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:29:24

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:29:40

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402A62839E-RF Tester:Loge Long
Date: 18.DEC.2024 15:29:56

***** END *****