

INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Wireless Charging + Bluetooth + NFC



INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Wireless Charging + Bluetooth + NFC



INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

USB Charging + Bluetooth + NFC



INTERTEK TESTING SERVICE

Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

USB Charging + Bluetooth + NFC



INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Wireless Charging + Bluetooth + Chip Insert



INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Wireless Charging + Bluetooth + Chip Insert



INTERTEK TESTING SERVICE


Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

USB Charging + Bluetooth + Chip Insert



INTERTEK TESTING SERVICE

Report No: HK20100359

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

USB Charging + Bluetooth + Chip Insert

