

Medtronic

Oct 7, 2016

RE: Tune up Procedure.

To whom it may concern

For FCC ID: LF524970A

The CareLink SmartSync Device Manager Base Model 24970A does not have a user accessible means of adjustment. Tune up procedures are performed during the manufacturing process.

Sincerely

A handwritten signature in blue ink, appearing to read 'Daniel Johnson', is written over a light blue horizontal line.

Daniel Johnson

RF Regulatory Affairs Specialist

Medtronic Inc.
8200 Coral Sea Street NE
Mounds View MN 55112