

Cal/Amp®


IMEI: 123456789012345



FCC ID: APV-H3640LA

IC: 5843C-H3640LA

IFETEL: RTIBOHM18-1830



ESN: 1234567890

CalAmp MFG P/N: HMU3640LA

WVWY

Assembled in China

CALIFORNIA PROPOSITION 65



WARNING


For more information, visit: www.p65warnings.ca.gov

0 Inch 1/32" 1 2 3 4 5 6 7 8

17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38

Cal/Amp®


IMEI: 123456789012345



FCC ID: APV-H3640LA

IC: 5843C-H3640LA

IFETEL: RTIBOHM18-1830



ESN: 1234567890

CalAmp MFG P/N: HMU3640LA


WVYY Assembled in China

CALIFORNIA PROPOSITION 65



WARNING:

Exposure to radio frequency fields may cause heating of the body.





Cal/Amp®

IMEI: 123456789012345

FCC ID: APV-H08A0LA
C: 3945C-H08A0LA
PTEL: RTBCH-M15-1820

ESN: 1234567890

Callamp MFG PIN: PMJ08A0LA
WYNY
Assembled in China

CAL/AMP ELECTRONICS, INC.
© 2008





Cal/Amp®

IMEI: 123456789012345

FCC ID: APV-H3640LA

IC: 5843C-H3640LA

IFETEL: RTIBOHM18-1830

ESN: 1234567890


CalAmp MFG P/N: HMU3640LA

WWWW Assembled in China

CALIFORNIA PROPOSITION 65

WARNING

For more information, please visit: www.P65Warnings.org





Cal/Amp®


IMEI: 123456789012345



FCC ID: APV-H0840LA

IC: 5840C-H0840LA

IFETEL: RTBCHM18-1830



ESN: 1234567890

Cal/Amp MFG. P/N: HML0640LA

WYYY Assembled in China

CAL/AMP ELECTRONICS

© 2000

Printed in the United States of America



