



POSITION - LEFT CABLE




Label to be wrapped around the left cable, see packaging 3D for exact positioning.
Label should be attached to the cable using the small centre tab only, the two larger sections should then be joined neatly together so the glue sides match and align exactly.

LABEL ADHESIVE




Adhesive should only be added to the two rectangle parts so they can be fixed together, no adhesive should be put on the centre joining part that wraps around the cable, see blue area above.



do not print



print this version

Material 3M 7818		FINISH CMYK as above				COPYRIGHT © 2019	
						DRAWN BY KH	DATE 04/02/2019
Bowers & Wilkins		DIMENSIONS IN mm	SCALE	ISS		PART NUMBER	
		TOLERANCES 0. ± 0.5 0.0 ± 0.3 0.00± 0.1		USED ON		SAP ART NUMBER	
				TITLE:- DRAFT GLOBAL - PI3 Cable Rating Label			