



Intertek Testing Services

ETL SEMKO

Report No.: 02158191
Talk Mode

Tested By: Hong, Report No.: 02158191

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698

dBuV



FCC15B



Intertek Testing Services

ETL SEMKO

Report No.: 02158191
Talk Mode

Tested By: Hong, Report No.: 02158191

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

25.06000	26.8	48.0
----------	------	------

* limit exceeded