

Mike Kuo

From: wklo@ccsemc.com.tw
Sent: June 16 2004 2:09 AM
To: Mike Kuo
Cc: CCS-Taiwan, Ting (E-mail); amanda@ccsemc.com.tw; kelsey@ccsemc.com.tw; harris@ccsemc.com.tw; cert@ccsemc.com.tw
Subject: 回信 : FW: TWINHEAD INTERNATIONAL CORP., FCC ID: FKGE14B, Assessment NO.: AN04T3926

Hi Mike,

Here are the replies.

Question #1: Internal photos are not clear. Please retake internal photos and make sure the photos can show all the component values.

Ans #1: The internal photos with clearly-shown component values are re-taken as attached.

Question #2: Block diagram file submitted contain schematic diagram as well, and schematic diagram file only contain certain portion of mother board. Please review the block diagram file that you submitted and delete schematic diagram from this file. Review the schematic diagram file to include all notebook computer portion of schematic diagram as well as for WLAN portion of schematic diagram. Submit schematic diagram again.

Ans #2: The schematic diagram is revised as attached.

Question #3: Operational description file only contain antenna location information which does not comply operational description information required. Please submit operational description again.

Ans #3: A revised operational description is attached.

Question #4: Page 12 of test report for 6dB bandwidth measurement, the unit of measurement does not match with the spectrum plots. Please make necessary correction.

Ans #4: Correction is made. Please refer to the revised test report below.

Question #5: Please take look section 7.5 of test report. This is mobile device with 20 cm separation distance from antenna to the body of user, so MPE is applicable and estimation is included in the test report. SAR is not applicable due to this device is mobile device not because it is below the low threshold.

Ans #5: This is a typo. The "MPE Evaluation" option is checked. Please refer to **Page 39** of the revised test report attached in **Ans #4**.

Question #6: The description contains in section 3.5 of test report does not agree that actual test channel. Please make necessary correction.

Ans #6: Correction is made. Please refer to the revised test report attached in **Ans #4**.

Question #7: Please take external photos to show the cable of ac/dc adapter. Need to confirm any special accessory used on the cable.

Ans #7: The external photos are re-taken as requested.

6/16/2004

Question #8: Please provide user manual for notebook computer include WLAN information and RF exposure information. The submitted user manual is for WLAN module which is not applicable to this device.

Ans #8: A revised user manual is attached.

Thank you for your advice.

Best Rgds,
WK

Mike Kuo <MKUO@CCSEMC.com>

收件人: "CCS-Taiwan, Ting (E-mail)" <ting@ccsemc.com.tw>, "CCS-Taiwan, Wklo (E-mail)" <wklo@ccsemc.com.tw>

2004/06/16 02:55 PM

副本抄送:

主旨: FW: TWINHEAD INTERNATIONAL CORP., FCC ID: FKGE14B, ?Assessment NO ? ? ? ?.: AN04T3926

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]

Sent: Tuesday, June 15, 2004 11:37 PM

To: mkuo@ccsemc.com

Subject: TWINHEAD INTERNATIONAL CORP., FCC ID: FKGE14B, Assessment NO.: AN04T3926

Question #1: Internal photos are not clear. Please retake internal photos and make sure the photos can show all the component values.

Question #2: Block diagram file submitted contain schematic diagram as well, and schematic diagram file only contain certain portion of mother board. Please review the block diagram file that you submitted and delete schematic diagram from this file. Review the schematic diagram file to include all notebook computer portion of schematic diagram as well as for WLAN portion of schematic diagram. Submit schematic diagram again.

Question #3: Operational description file only contain antenna location information which does not comply operational description information required. Please submit operational description again.

Question #4: Page 12 of test report for 6dB bandwidth measurement, the unit of measurement does not match with the spectrum plots. Please make necessary correction.

Question #5: Please take look section 7.5 of test report. This is mobile device with 20 cm separation distance from antenna to the body of user, so MPE is applicable and estimation is included in the test report. SAR is not applicable due to this device is mobile device not because it is below the low threshold.

6/16/2004

Question #6: The description contains in section 3.5 of test report does not agree that actual test channel. Please make necessary correction.

Question #7: Please take external photos to show the cable of ac/dc adapter. Need to confirm any special accessory used on the cable.

Question #8 : Please provide user manual for notebook computer include WLAN information and RF exposure information. The submitted user manual is for WLAN module which is not applicable to this device.

Best Regards

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

6/16/2004