

## Helen Zhao

---

**To:** ???  
**Subject:** RE: Hantel Co., Ltd., FCC ID: ODGCLIENTPAGER, Assessment NO.: AN06T6219, Notice#1

-----Original Message-----

From: cgyloves@hct.co.kr [mailto:cgyloves@hct.co.kr]  
Sent: Thursday, October 12, 2006 11:03 PM  
To: Helen Zhao  
Subject: Re: Hantel Co., Ltd., FCC ID: ODGCLIENTPAGER, Assessment NO.: AN06T6219, Notice#1

Dear Helen,

I've attached the new report. Please check it.  
Thank you.

Best Regards,  
CHA

-----Original Message-----

Sent: Wednesday, October 11, 2006 5:40 PM  
Subject: Hantel Co., Ltd., FCC ID: ODGCLIENTPAGER, Assessment NO.: AN06T6219, Notice#1

Question #1: The test report indicates the receiving frequency is from 929MHz to 932MHz. Based on FCC15.31, you need to test 2 frequencies, one near top and 1 near bottom. But the test report shows only 929MHz (near bottom) has been tested. Please explain.

Thank you,  
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

>