

1) Please provide information on DC voltage/current into final RF stage, per 2.1033(c)(8).

3.6 volts at 2000 milliamperes maximum for 824 to 849 MHz power amp;
3.6 volts at 1500 milliamperes maximum for 1850 to 1919 MHz power amplifier.

2) Please provide tune-up information, per 2.1033(c)(9).

There are no mechanical tuning adjustments within the radio.
Automated factory calibration program adjusts internal frequency standard, receive AGC, and transmit power levels, which are stored in non volatile RAM.

John C Papson, Principal RF Engineer
Telular Corporation
580 Old Willets Path
Hauppauge, NY, USA 11788
Voice: (631) 232-6070 ex213
Fax: (631) 232 6082
Email: jpapson@telular.com