




51.




52.



53.




54.



55.

07:53:07 FEB 15, 2001

REF 30.5 dBm #AT 30 dB

MKR 1.9813 GHz
12.68 dBmPEAK
LOG
10
dB/
OFFST
20.5
dB
DL
-13.0
dBmMA SB
SC FC
CORRCENTER 1.9600 GHz
#RES BW 1.0 MHz


VBW 300 kHz

SPAN 100.0 MHz
SWP 20.0 msec

56.

07:53:26 FEB 15, 2001


REF 30.5 dBm #AT 30 dB

MKR 1.9815 GHz
12.68 dBmPEAK
LOG
10
dB/
OFFST
20.5
dB
DL
-13.0
dBmMA SB
SC FC
CORRCENTER 1.9600 GHz
#RES BW 1.0 MHz


VBW 300 kHz

SPAN 200.0 MHz
SWP 20.0 msec

57.



58.




59.

07:57:21 FEB 15, 2001

MKR 1.96000 GHz
19.23 dBm

REF 30.5 dBm #AT 30 dB

PEAK
LOG
10
dB/
OFFST
20.5
dB
DL
-13.0
dBm



CENTER 1.96000 GHz
#RES BW 1.0 MHz

VBW 300 kHz

SPAN 20.00 MHz
SWP 20.0 msec


60.

07:56:48 FEB 15, 2001

MKR 1.96000 GHz
9.44 dBm

REF 30.5 dBm #AT 30 dB

PEAK
LOG
10
dB/
OFFST
20.5
dB
DL
-13.0
dBm



CENTER 1.96000 GHz
#RES BW 1.0 MHz

VBW 300 kHz

SPAN 20.00 MHz
SWP 20.0 msec

