



DIGI INTERNATIONAL
11001 Bren Road East
Minnetonka, MN 55343
952-912-3444 tel
952-912-4991 central fax

Date: 13 April 2016

To Whom It May Concern

Subject: Description of changes to device

Applicant: Digi International Inc.
FCC ID: MCQ-PS2CSM

To Whom It May Concern:

This Class II Permissive Change adds a new firmware option which uses an RF duty cycle of up to 66%. The original certification was based on the original firmware which has a duty cycle of 27%. As explained in the operational description, the firmware loaded onto the device restricts channels as required for band edge compliance at the applicable duty cycle. Antenna loss tables have also been updated.

There are no changes to the hardware and no changes to the RF characteristics of the signal other than the duty cycle.

Regards,

Paul Dahl
Hardware Manager