

.....

4085 Howard Rd
Dayton, MD 21936

TRP Inc.

September 27, 2005

FCC Laboratory
7435 Oakland Mills Rd
Columbia, MD 21036

Gentlemen:

Submitted herewith is a request for certification of a Medical Implant Communications system Home Monitoring transmitter, FCC ID:LF5MICSW, that is part of a Medical Implant Communications System.

Due to small size of the unit, space limitations on the bottom label, and numerous regulatory label requirements, it is requested that permission be given to locating the Part 2, Part 95 and Part 15 warning statements in the instruction manual. The FCC ID will appear on a label on the equipment.

If you have any questions, please call Phillip Inglis at 410 531 3439 or contact via email at jinglis@erols.com. It is also requested that you forward copies of any correspondence and authorization documents to the email address specified above.

Sincerely,

Phillip Inglis
Consultant

.....