



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52



Page 1 of 6



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52


Page 2 of 6



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52



Page 3 of 6



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52



Page 4 of 6



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52

Page 5 of 6



Internal Photos Documentation

Applicant: Rollease Acmeda Inc
Product: DCFT 15 ARC Motor
FCC ID: 2AGGZ003B9ACA52
IC: 21769-003B9ACA52

Page 6 of 6

