



n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -37.71dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:39:09

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.02dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:37:16

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -37.83dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:38:13

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -37.93dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:42:01

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -37.63dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:40:11

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.14dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:41:06

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -37.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:44:54

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -37.61dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:43:04

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -37.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:44:00

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -37.80dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:47:44

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.37dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:45:54

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -37.62dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:46:50

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -38.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:50:40

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -37.51dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:48:47

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -37.51dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:49:45

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -37.54dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:51:43

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -37.65dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:52:39

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -37.49dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:53:34

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:54:35

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -37.05dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:55:31

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -37.52dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:56:26

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@0 -37.61dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:57:26

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -37.16dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:58:22

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -37.60dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 09:59:16

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -38.01dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:00:20

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -37.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:01:17

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -37.36dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:02:13

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.72dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:03:15

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -37.38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:04:13

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -38.20dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:05:08

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@0 -38.18dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:06:11

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -37.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:07:09

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -37.52dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:08:04

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.82dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:09:10

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -38.18dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:10:07


n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -37.50dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:11:04


n78_3

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -35.50dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:10:40

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@23 -36.46dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:11:38

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -36.65dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:12:40

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.79dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:13:57

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@23 -35.49dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:14:56

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB24@0 -35.97dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaister Liang
Date: 11.DEC.2024 11:03:51

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@0 -36.01dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:04:56

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23 -35.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:05:59

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0 -35.93dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:07:12

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.51dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 09:35:38

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 09:36:32

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.07dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 09:37:27

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.02dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 09:56:31

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@37 -35.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 09:57:28

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB36@0 -36.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:29:53

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:31:00

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.30dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:32:02

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.68dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 15:33:03

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -36.44dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:01:10

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@50 -35.62dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:02:06

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -36.42dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:03:01

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.13dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:04:08

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@50 -36.32dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:05:05

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB50@0 -36.01dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 10:06:02

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@0 -36.47dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 10:07:04

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50 -36.18dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 10:08:01

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0 -35.41dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 10:08:57

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -36.28dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 10:50:47

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@77 -35.83dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 10:51:45

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -36.04dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:06:12