

August 11, 2005

RE: BEHAVIOR TECH COMPUTER CORP

FCC ID: E5XMSM873AU

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The test program used did not appear to support input from the EUT. Please explain/correct as necessary. (ANSI C63.4 section 6.1 and 11.1).
- Cable positioning for the keyboard does not appear to necessarily following ANSI C63.4 2003, 6.2.1.2. See NOTE contained in this section. Please review, comment, and/or correct as necessary.

Timothy R. Johnson Examining Engineer

mailto: tjohnson@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.