

FUNCTIONAL DESCRIPTION

The 5882-4 is identical in function and operation to the Ademco 5881EN receiver; (FCC ID: CFS8DL5881EN) The reason for this new product is that the 'DIP' package - receiver chip is obsolete, and no longer being produced. The new surface mount package required a re-layout of the RF paths.