

MODEL : Corecess 3113



FCC ID: QB3CORECESS 3113

Equipment Name: Ethernet ADSL Modem

Electrical Rating: DC 9V, MAX 1.0A

Complies with Part 68 Rules

US: CS2DL04B3113

REN: 0.4B Jack Type: RJ11 Jack

Trade Name or Applicant : Corecess Inc.

Manufacture and Nation : Corecess Inc. / Republic of KOREA

Serial No.:



この装置は、情報処理装置等電波障害自主規制協議会（VCCI）の基準に基づくクラスA情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference., And (2) this device must accept any interference received, including interference that may cause undesired operation.

(1) This equipment complies with Part 68 of the FCC rules. On the Bottom of this equipment is a label that contains, among other information, the FCC registration number for this equipment. If requested, provide information to your telephone company. (2) If your Corecess 3113 causes harm to the telephone network, the Telephone Company may discontinue your service temporarily. If possible, they will notify you in advance. But if advance notice isn't practical, you will be notified as soon as possible. You will be advised of your right to file a complaint with the FCC. (3) Your telephone company may make changes in its facilities, equipment, operations, or procedures that could affect the proper operation of your equipment. If they do, you will be given advance notice so as to give you an opportunity to maintain uninterrupted service. (4) If you experience trouble with this equipment, Corecess 3113, please contact local Corecess Global representative, for repair and warranty information. The telephone company may ask you to disconnect this equipment from the network until the problem has been corrected or you are sure that the equipment is not malfunctioning. (5) There are no repairs that can be made by the customer to the Corecess 3113.