

FCC TEST REPORT Report No. : FG552401

Appendix C. Set up Photograph

Spurious Radiation




FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2 Issued Date : Jun. 07, 2005





Frequency Stability

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2 Issued Date : Jun. 07, 2005