



Label Location Justification

Date: 13 July 2022

Federal Communication Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

FCC ID: 2ASJH-RVSWT101

To whom it may concern,

The device is shipped without the rear cover on it. The rear cover is intended to be fixed on the wall via two screws, and it is used as a mounting bracket of the device. Therefore, the label is visible to the user when the device is not mounted on the wall such as when replacing its battery.

Regards,

A handwritten signature in blue ink, appearing to read "Cecilio Dimasacat".

Cecilio Dimasacat 13-07-2022
Compliance Engineer
Tel. +61 3 92138428
Email: cecilio.dimasacat@setec.com.au



Setec BMAPRO

19 Henderson Road, Knoxfield, Victoria 3180, AUSTRALIA

SETEC.COM.AU | TEAMBMAPRO.COM

PHONE +61 3 9763 0962 | **EMAIL** admin@setec.com.au | admin@teambmapro.com

ACN 646 354 127 | **ABN** 59 646 354 127