



Microhard Systems Inc.

Leaders in Wireless Telecom

#110, 1144 - 29th Avenue N.E.

Calgary, Alberta T2E 7P1

Tel: (403) 248-0028

Fax: (403) 248-2762

Website: <http://www.microhardcorp.com>

FCC ID: NS900P4

June 14, 2002

Federal Communications Commission
OET Laboratory Division.
7435 Oakland Mills Rd.
Columbia, MD 21046

Re: Overview of Engineering Changes

The following are an overview of the changes made to the MHX-2400:

- Use MCX or Reverse SMA connector
- Digital Temperature compensation option
- Reset circuit for microprocessor
- Inner shield for VCO circuit
- VCO buffer circuit changed with compatible part.
- Output Match Optimized
- PA DAC changed vendors
- Added Antennas to test set

Please note that the Bill of Material and Schematics have been updated to reflect these changes.

Regards,

Hany H. Shenouda
Director of Engineering