



Mode:LW004-PB

Radiated Measurement (Below 1GHz)



Radiated Measurement (Above 1GHz)



RF Conducted



CONDUCTED EMISSION TEST SETUP

