

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1



Photo 2

Worst Case Position

ECU

Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)
X-axis



Y-axis



Z-axis



Outside Antenna

Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)
X-axis



Y-axis



Z-axis



Worst Case Position

Inside Antenna

Below 30 MHz: X-axis

Above 30 MHz (Horizontal: X / Vertical: X)

X-axis



Y-axis



Z-axis



Rear Antenna

Below 30 MHz: X-axis

Above 30 MHz (Horizontal: X / Vertical: X)

X-axis



Y-axis



Z-axis



Worst Case Position

Immobilizer Antenna

Below 30 MHz: X-axis

Above 30 MHz (Horizontal: X / Vertical: X)

X-axis



Y-axis



Z-axis



Worst Case Position



With key



Without key (Worst)

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124