

SETUP PHOTOS 10.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





END OF REPORT