





802.11n HT40




Date: 9.NOV.2018 00:35:52

802.11ac VHT20




Date: 8.NOV.2018 23:53:37

802.11ac VHT40




802.11ac VHT80




MIMO <Ant. 1>

802.11a




Date: 7.NOV.2018 20:19:38


802.11n HT20




Date: 7.NOV.2018 21:14:01

802.11n HT40



Date: 8.NOV.2018 00:31:13

802.11ac VHT20



Date: 7.NOV.2018 23:37:31

802.11ac VHT40



Date: 7.NOV.2018 23:47:29

802.11ac VHT80


Date: 8.NOV.2018 00:05:46

MIMO <Ant. 2>
802.11a



Date: 7.NOV.2018 20:21:20

802.11n HT20


Date: 7.NOV.2018 21:15:00




802.11n HT40



Date: 7.NOV.2018 21:41:01

802.11ac VHT20



Date: 7.NOV.2018 23:38:23



Report No. : FR8N0132-01E

