



n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -37.77dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:11:09

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@0 -37.62dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:09:10

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -38.03dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:10:10

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -37.57dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:14:15

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0 -37.60dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:12:17

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -37.53dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:13:16

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -38.09dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:17:19

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -38.31dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:15:20

n77_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -37.99dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:16:20

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -37.81dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:20:22

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@0 -37.57dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:18:25

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.95dBm




ProjectNo.: 2401Z104805E-RF Testet: Rungfunester Liang
Date: 7 DEC 2024 13:19:24

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -38.07dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:23:26

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0 -38.14dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:21:29

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -38.27dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:22:28

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -38.20dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:26:27

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.56dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:24:30

n77_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -38.24dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7 DEC 2024 13:25:30

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -37.66dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:29:28

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@0 -37.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:27:31

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -37.77dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:28:30

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0 -38.09dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:30:34

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:31:33

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumeater Liang
Date: 7.DEC.2024 13:32:32

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.98dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:33:36

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@216 -38dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:34:35

n77_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0 -38.22dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:35:33

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@0 -37.90dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:36:37

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216 -38.06dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:37:37

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0 -37.92dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmeter: Liang
Date: 7.DEC.2024 13:38:35

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0 -38.53dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:39:42

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -38.39dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:40:42

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -38.23dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:41:40

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.91dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:42:45

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -38.06dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:43:45

n77_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -37.63dBm




ProjectNo.: 2401Z104805E-RF Testset: Rungfunmaster: Liang
Date: 7 DEC 2024 13:44:44

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@0 -37.65dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:45:49

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -38.12dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:46:49

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -38.19dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:47:48

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:48:58

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -37.69dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:49:58


n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -37.84dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 7 DEC 2024 13:50:57

n77_3


n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -34.15dBm




n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@23 -33.25dBm




n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -33.25dBm




n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.32dBm




n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@23 -33.73dBm



n77_3_10MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB24@0 -33.87dBm




n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@0 -33.63dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:04:32

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@23 -33.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:05:28

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB24@0 -33.77dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:06:24

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -33.64dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:07:28

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@37 -33.92dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:08:25

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -33.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:09:22

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.66dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:10:24

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@37 -33.28dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:11:21

n77_3_15MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB36@0 -33.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:12:18

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@0 -32.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:13:19

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@37 -33.33dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:14:16

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB36@0 -33.55dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:15:12

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -33.77dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:16:23

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@50 -33.93dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:17:20

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -33.28dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:18:16

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@0 -33.76dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:19:18

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB1@50 -33.37dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:20:15

n77_3_20MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB50@0 -33.14dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 13:21:12