



FCC Part 27N&IC RSS 130

B71, Normal
1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~7.98GHz)




5MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




5MHz_High_QPSK_1@0(30MHz~7.98GHz)




10MHz_Low_QPSK_1@0(30MHz~7.98GHz)




10MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



10MHz_High_QPSK_1@0(30MHz~7.98GHz)




15MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:02:21

15MHz_Middle_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:02:37

15MHz_High_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:02:53

20MHz_Low_QPSK_1@0(30MHz~7.98GHz)




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:03:11

20MHz_Middle_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:03:27

20MHz_High_QPSK_1@0(30MHz~7.98GHz)



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 23.JAN.2025 15:03:42

***** END *****