


Component side view of Power Board II




ETL Inc. #584 Sangwhal-ri, Kanam-myon, Yoju-kun, Kyounggi-do, 469-885, Korea



FCC ID: OIOEPM-4200 Report No: E03.0701.FCC.378N Date of issue: July 01, 2003

Solder side view of Power Board II




ETL Inc. #584 Sangwhal-ri, Kanam-myon, Yoju-kun, Kyounggi-do, 469-885, Korea



Component side view of Power Board III



Solder side view of Power Board III




ETL Inc. #584 Sangwhal-ri, Kanam-myon, Yoju-kun, Kyounggi-do, 469-885, Korea



Component side view of AC POWER Switch Board



Solder side view of AC POWER Switch Board



ETL Inc. #584 Sangwhal-ri, Kanam-myon, Yoju-kun, Kyounggi-do, 469-885, Korea



FCC ID: OIOEPM-4200 Report No: E03.0701.FCC.378N Date of issue: July 01, 2003

Component side view of PDP PANEL



Solder side view of PDP PANEL



ETL Inc. #584 Sangwhal-ri, Kanam-myon, Yoju-kun, Kyounggi-do, 469-885, Korea