

1. Please provide an internal photo of the bottom side of the PCB.

I have revised our internal photographs file to include now both photo of connector side and display side of PWB.

2. The theory of operation states that a Stereo FM receiver is contained in the device. Please note that this makes the device a part 15 device also subject to the FM receiver requirements of Part 15. As such the appropriate Part 15 statements must be on the device unless the exception of 15.19(a)(5) can be met. Please note that the label and device appears large enough to contain the required 15.19(a)(1) statement. Please revise the FCC ID label to incorporate this statement. Alternately, please provide evidence that the product can meet the exception of 15.19(a)(5) (i.e. device too small or it is not practical to place the statement on the device). Please note, you must provide sufficient cause in order to have the label in the manual and not on the device (size being the primary factor).

As already requested, we still do not see any possibility to include part 15 text into the device itself. Back cover is not fixed into device, and internal antenna area should not be covered. As can be seen from external photos, there is room neither for a bigger label nor for a legible long text. Therefore, our opinion is that this device fulfills both requirements for placing part 15 text onto the manual.

3. Your manual does not appear to contain the SAR values for this phone. Please note that the FCC states that these values are to be provided to the user in the manual. Please list the SA values for head and body SAR as measured in the SAR report.

Unless I have uploaded an obsoleted version of user manual, SAR values are available at page 152.