

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621

## EXTERNAL PHOTOGRAPHS



**Figure 1. Top of EUT**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 2. Back of EUT and Back of Antenna Enclosure**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 3. Left Side of EUT**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 4. Right Side of EUT**



US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 5. Front of EUT and Front of Antenna Enclosure**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 6. Bottom of EUT**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 95  
KE3-30035901  
23-0066  
May 11, 2023  
Radio Systems Corporation  
RFA-621



**Figure 7. Close up of Battery Compartment**