



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 20, 2004

RE: Telematics Wireless Ltd.

FCC ID: NTAFP100SA

I have a few comments on the above referenced Application.

- 1) In regards to your previous response to item 5. The device also contains a 915 MHz SAW resonator that was not listed. Although this frequency is part of the transmitter (licensed), it also appears to function as part of the receiver (unlicensed), each applicable to their own limits. Additionally, 15.33(b)(1) discusses the highest frequency generated or used in the device or on which the device operates or tunes (MHz). Note that the device tunes to 915 MHz. Therefore, in a receive mode of operations, unless the device is a super-het. receiver as given by 15.33(b)(3), the ranges of measurements should follow this table. Therefore this gives an upper range of measurement of 5 GHz. Also note test requirements/setup typically specified by ANSI C63.4 Section 12, and 12.1.1.2.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.