

dward ATCB

From: wendy@adt.com.tw
Sent: Sunday, November 28, 2004 11:38 PM
To: dward@atcb.com
Cc: stephanie@adt.com.tw
Subject: 回信: RE: Solve the comment for FCC ID.: H8NWLL4030



11-28
L4030_ATCB Comm

Dear Dennis

This project is for FCC class II permissive change by the software.
The difference compared with the original design is adding the turbo mode of 5GHz to this EUT for the test.
So the original application do not tested for the turbo.

Regarding the item 2 of the comment, the test report has been revised and uploaded to website.
Please check.
Thanks for your assistance!

Best Regards
Wendy Liao

Wendy Liao (廖意紋)/ ADT Corp.
TEL: 03-318-3232 EXT 1625
FAX: 03-318-5050
Email: wendy@adt.com.tw
地址: 桃園縣龜山鄉文化村華亞二路 1 9 號

"dward ATCB"
<dward@atcb.com>

收件人

2004/11/28 下午
06:21

<wendy@adt.com.tw>,
<ellis@adt.com.tw>,
<stephanie@adt.com.tw>

副本抄送

請回信 給

'陳鴻達' <major@tradeint.com.tw>

<dward@atcb.com>

主旨

RE: H8NWLL4030

HI Ellis
Please see comments
Thanks

Dennis Ward

ATCB

Phone - Headquarters (703) 847-4700

Phone - Dt Associates (209) 966-2145

Phone -Alternate business (703) 880-4841 (See attached file: 11-28 H8NWLL4030_ATCB
Comments.pdf)