



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch  
香港商立德國際商品試驗有限公司 桃園分公司

No. 19, Hwa Ya 2nd Rd., Wen Hwa Tsuen, Kwei Shan Hsiang, Taoyuan Hsien 33383, Taiwan

TEL: 886-3-3183232 FAX: 886-3-3270892

www.bureauveritas-adt.com / E-mail: [service.adt@tw.bureauveritas.com](mailto:service.adt@tw.bureauveritas.com)

January 25, 2019

**Cover Letter for re-use of Test Data**

The initial application has been granted according to 47CFR Part 15C& Part 15E in December 19 of 2018, with the FCC ID: I46-INA-WIFIUSB-4

The new equipment to be Granted in this new application, according to FCC ID: PANCL8822BUV2, only differs from the difference compared with original report is changing the product name, model name, brand name, applicant and the logo printing of housing to apply a new FCC ID

The lab re-test All power and spot check worst channel emission, FCC ID: PANCL8822BUV2 is not worst than FCC ID: I46-INA-WIFIUSB-4

We have done a spot check, the changes described above do not affect the radio characteristics of the equipment. results, radio test data retrieved from the initial application FCC ID : I46-INA-WIFIUSB-4 can be re-used for the FCC ID : PANCL8822BUV2 equipment.

If you have any questions, feel free to contact us. Thank you.

Regards,

Jamison Chan, Title

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-260 0694

Fax: 886-3-327 0892

Email: [Jamison.Chan@tw.bureauveritas.com](mailto:Jamison.Chan@tw.bureauveritas.com)

Difference logo printing of housing

FCC ID: I46-INA-WIFIUSB-4



FCC ID: PANCL8822BUV2

