## FCC Class II Permissive Change Request Letter

Date: 12/1//2024

To FCC:

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046 USA

## RE: FCC Permissive II Change Request for Company: Yardi Systems Inc. FCC ID: 2BAL9YDIZW

We are submitting an application for an FCC, Class II permissive change of the Company name: Yardi Systems Inc., product description: RentCafe Home IQ Hub (FCC: **2BAL9YDIZW**, Original Grant Date: **10/3/2024**). The transmitter itself has not changed. The changes do not affect any RF circuitry. These are only DC power changes and removal of the LTE modem Reset. The Reset is redundant and was causing issues with the modem POR.

Change to the Base Module Bill of Material:

Component Change	Yardi PN	MFG PN
Remove U14 OD buffer	303-00107-010	74LVC1G07GS
Remove R32 and R33 USB pull downs 15K resistors	200-15004-111	CRCW040215K0FKED
Change C44 from 100uF/700mohm TANT cap to		
470uF/100mohm TANT cap	206-00477-240	T495X477K010ATE100
Change C52 from 100uF/700mohm TANT cap to	206-00107-244	T495D107K016ATE100
100uF/100mOhm TANT cap		
Change R20 from 15K to 10K resistor	200-10004-111	CRCW040210K0FKED

Sincerely,

Title Senior Vice President, General Counsel Name: Arnold Brier Address 430 Fairview Ave Goleta CA 93117

Signature

an