

## INTERTEK TESTING SERVICES

---


### Internal photos



## INTERTEK TESTING SERVICES

---



### Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos







## INTERTEK TESTING SERVICES

---


### Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos





---

Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020



## Internal photos





Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020




## INTERTEK TESTING SERVICES

### Internal photos



Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020

## Internal photos




Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020



## INTERTEK TESTING SERVICES

---

### Internal photos




---

Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020

## INTERTEK TESTING SERVICES

---

### Internal photos







## INTERTEK TESTING SERVICES


---

### Internal photos



## INTERTEK TESTING SERVICES

### Internal photos




Test Report Number: 17031818HKG-001  
FCC ID: G2R-6020  
IC: 1135D-6020



## INTERTEK TESTING SERVICES

---

### Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos

