



Report No.: TMWK2303000590KR




UNII-3 IEEE 802.11ax HE40 mode

5755 MHz




5795 MHz




UNII-3 IEEE 802.11ax HE80 mode

5775 MHz




Test Plots (OBW 99%)



Non-Beamforming: UNII-1 Chain 0




Report No.: TMWK2303000590KR





Report No.: TMWK2303000590KR



Report No.: TMWK2303000590KR




Report No.: TMWK2303000590KR



Report No.: TMWK2303000590KR


Non-Beamforming: UNII-1 Chain 1




Report No.: TMWK2303000590KR

UNII-1 IEEE 802.11n HT20 mode


5180 MHz





5220 MHz



5240 MHz




Report No.: TMWK2303000590KR




UNII-1 IEEE 802.11ax HE20 mode


5180 MHz





5220 MHz



5240 MHz




Report No.: TMWK2303000590KR




Report No.: TMWK2303000590KR

Test Plots (OBW 99%)



Non-Beamforming: UNII-2a Chain 0




Report No.: TMWK2303000590KR




Report No.: TMWK2303000590KR






Report No.: TMWK2303000590KR




Report No.: TMWK2303000590KR

UNII-2a IEEE 802.11ax HE40 mode

5270 MHz





5310 MHz



UNII-2a IEEE 802.11ax HE80 mode


5290 MHz





Report No.: TMWK2303000590KR


Non-Beamforming: UNII-2a Chain 1




Report No.: TMWK2303000590KR

UNII-2a IEEE 802.11n HT20 mode

5260 MHz





5300 MHz




5320 MHz




Report No.: TMWK2303000590KR








Report No.: TMWK2303000590KR



Report No.: TMWK2303000590KR







Report No.: TMWK2303000590KR

Test Plots (OBW 99%)

UNII-2c Chain 0



Report No.: TMWK2303000590KR



Report No.: TMWK2303000590KR

