

XIAMEN COMFORT SCIENCE & TECHNOLOGY GROUP CO., LTD.

(5/F) NO.168, QIANPU ROAD, SIMING DISTRICT, XIAMEN, CHINA

2019/4/19

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

List of Differences for FCC ID: YMX-EC806A

Location	Old PCB of FCC ID: YMX-EC806A	New PCB of FCC ID: YMX-EC806A
Handrail on the right	Side Board Controller PCBA: PCB:EC806A-Button-V1.0	Side Board Controller PCBA: EC806A-Button-V1.1 , add R22-R23, R24-R28, R18-R21, TVS, C3, C4-C5, ESD1-ESD4
Upper (back) of the mandrel	Core drive plate:	Add material: 1. C60-69, Ceramic capacitor 2. L10, common mode choke 3. C75-80, C122, chip resistor 4. L1-L3, common mode choke delete: 1. CE2, Aluminium electrolytic capacitor 2. R87, 187, R88, 188, chip resistor 3. FB9-14, Magnetic beads
Seat subordinate	Pedestal adapter plate	delete : 1. Remove R610K Resistance 2. Removal of Q2 5551 triode Add material : Increase ESD1-ESD3
Armrest	USB charging board	Change of USB Charging Board Layout
Back movement	Protract Motor: ZYT-56S-1-2E, DC24V	Protract Motor: ZYT-56S-1-6E, DC24V
Back movement	Up-down motor : ZYT-56S-1-4E , DC24V	Up-down motor : ZYT-56S-1-8E , DC24V
Back movement	Knead motor : ZYT-56S-1-3E , DC24V	Knead motor : ZYT-56S-1-7E , DC24V

Sincerely,

XIAMEN COMFORT SCIENCE & TECHNOLOGY GROUP CO., LTD.**Pengfei Cui/ Safety Engineer**