Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: <u>2AC5R-SC-64SW</u>

Date: July 04, 2018

To The Commission:

This change of Identification request applies for a new FCC ID: **2AC5R-SC-64SW** as established in 47CFR 2.933(b) for a currently approved device. This application by **SUPERSONIC INC** will establish a new FCC ID under **SUPERSONIC INC** Grantee code for purpose of marketing. The original grant to **Sky Phone LLC** will remain in effect.

An authorization letter by **Sky Phone LLC** attached. Per 2.933(b)

- 1. The original identification is **FCC ID: <u>2ABOSSKYWATCH1</u>**
- 2. The original grant date is 07/24/2016
- 3. The equipment is identical to the original equipment.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

FCC ID label and label location External photographs Letter of Change FCC ID Authorization Letter for FCC ID User Manual Product Equality Declaration

Sincerely,

Client's name / title : David Gholiani /CEO

Daird Choliani

Contact information / address: 6555 BANDINI BOULEVARD COMMERCE CA 90040-3119

USA

Tel: +323 201 5060 *Fax:* +323-201-5069

E-mail: David@SupersonicINC.com